

	Type	L #	Hits	Search Text	DBs	Time Stamp	Comments	Error Definition	Errors
1	BRS	L1	1	computer and ((smart adj card) same fan same air)	USPA T	2003/12/1 9 09:36			0
2	BRS	L2	184	computer and ((card) same fan same air)	USPA T	2003/12/1 9 09:35			0
3	BRS	L3	10	computer and ((card) same fan same air)	JPO	2003/12/1 9 09:35			0
4	BRS	L4	2	computer and ((smart adj card) same fan same air)	US-P GPUB ; EPO; JPO; DERW ENT; IBM- TDB	2003/12/1 9 09:37			0

	Type	L #	Hits	Search Text	DBs	Time Stamp	Comments	Error Definition	Errors
1	BRS	L1	322	(processor or chip) and (fan same damp\$4)	USPA T	2003/12/1 9 10:26			0
2	BRS	L2	24	(processor or chip) and (fan same damp\$4)	JPO	2003/12/1 9 10:26			0
3	BRS	L3	8	(processor or chip) and (fan same vibration)	JPO	2003/12/1 9 10:28			0
4	BRS	L4	22	(processor or chip) and (fan same vibration)	EPO; DERW ENT; IBM_ TDB	2003/12/1 9 10:30			0
5	BRS	L5	44	computer and (fan same vibration)	EPO; DERW ENT; IBM_ TDB	2003/12/1 9 10:32			0
6	BRS	L6	293	computer and (fan same vibration)	USPA T	2003/12/1 9 10:40			0
7	BRS	L7	276	6 not 1	USPA T	2003/12/1 9 10:32			0
8	BRS	L8	83	computer and (fan same washer\$1)	USPA T	2003/12/1 9 10:42			0
9	BRS	L9	2	computer and (fan same washer\$1)	JPO	2003/12/1 9 10:43			0
10	BRS	L10	11	computer and (fan same washer\$1)	EPO; DERW ENT; IBM_ TDB	2003/12/1 9 10:43			0